

## 5big Thunderbolt2 driver for Windows

Posted: December 8, 2014

### 1.1.3.1621-whql.zip (Downloads)

Please follow these installation instructions for **Windows 8**:

1. Click on the link above to download the file.
2. Disconnect the 5big's Thunderbolt cable so that it is not connected to the computer.
3. Extract the file.
4. For 64-bit operating systems: Open the **amd64** folder.  
For 32-bit operating systems: Open the **i386** folder.
5. Right-click on the **lcstor.inf** file and select **Install**.
6. Once the installation is complete, connect the 5big's Thunderbolt cable to the computer.
7. Format the drive according to the instructions found [here](#).

Please follow these installation instructions for **Windows 7**:

1. Click on the link above to download the file.
2. Disconnect the 5big's Thunderbolt cable so that it is not connected to the computer.
3. Extract the file.
4. Right-click on **Computer**, then select **Manage**.
5. Select **Device Manager**.
6. Paying close attention to the list of items, connect the 5big's Thunderbolt cable to the computer. Watch for a new item to appear in the list. It will probably appear as *Other Device > RAID Controller*.
7. Right-click on the new item and select **Update Driver Software...**
8. Select **Browse my computer for driver software**.
9. Browse to the location where you extracted the driver from step 3.  
For 64-bit operating systems: Select the **amd64** folder.  
For 32-bit operating systems: Select the **i386** folder.
10. Finish the installation.
11. Format the drive according to the instructions found [here](#).